



NOTES:
1. FUSE WIRING IS TYPICAL. ACTUAL MACHINES WILL VARY DEPENDING ON VOLTAGE. SEE MACHINE.

NOTES
1. TBB AND TBC ARE LOCATED IN THE RIGHT CONTROL BOX.

W6DR3FMTS

DRYER-GAS

MICRO 6 SYSTEMS MARK V

SCHMATIC: MOTORS + INCOMING VOLTAGES

SUPERCEEDS W6DR3FMTR FOR INVERTER DRIVEN BLOWER

PELLERIN MILNOR CORPORATION

W6DR3FMTS
2011305B